


### Mounting area:

The two basic types of mounting areas are:

1. axial access or "open" mounting area (see fig. 1)
2. grooved slot (see fig. 2)

Both types are used on the piston side as well as on the rod side.



Some sealing elements like glands or fiber reinforced seals with large cross sectional area basically call for an axially accessible mounting space for assembly. Axially accessible mounting spaces are also required in cases where assembly involves small diameters.